

Nordion (Canada) Inc. Event Reporting

For the Quarter (Jul to Sep 2023)

Event Number	Event	Status/Outcome
23-05*	GC-220 sample chamber stuck	The GC-220 sample chamber became temporarily stuck. The issue was resolved by cleaning the chamber assembly sliding mechanism. To avoid future reoccurrence, the frequency of regular inspection and maintenance has been increased. The GC-220 is designed such that the sealed source remain shielded at all times. As such, there were no health or safety impacts from this incident.
23-06*	Late reporting for a zirc shipment	Due to an internal administrative error, a report on the export of zirconium tubes was submitted 7-business days after shipment, outside the 5-business days required on the export license. To prevent reoccurrences, a more conservative internal requirement of 3-days is being administratively assigned to zirc licenses.

^{*} There was no impact to health, safety, environment or security as a result of these events