



Nordion Inc. Event Reporting

For the Quarter (July – September 2015)

Event Number	Event	Status/Outcome
15-10*	A container was received by customer showing evidence that the lid had been removed and replaced using duct tape.	No corrective action for Nordion. Customer to follow up with their carrier.
15-12*	Fire on roof of Kanata Operations Building.	A small fire on roof of the Kanata Operations Building due to roof work was quickly contained. Currently under investigation.
15-13*	Customer received a vial in which the screw cap was not seated properly. Product had escaped from the vial into the lead pot.	This is an isolated event. Nordion conducted an investigation and all personnel were made aware of the investigation and root cause. No further corrective action required.
15-14*	Carrier reported damage to a Type A package while in transit.	No action required by Nordion.
15-15*	Nordion did not include documentation relating to the CNSC export license for a shipment.	This was an administrative error. Currently under investigation.
15-16*	Customer did not receive one of their packages.	The carrier misplaced a customer package and notified local Regulators, who in turn advised that no further action was required. No action required by Nordion.
15-19*	Customer reported damaged transport package.	No corrective action for Nordion. Customer to follow up with their carrier.
15-23*	Product dose did not match package labeling and documentation.	Currently under investigation.

** There was no impact to health, safety, environment or security as a result of these events*