

Nordion(Canada) Inc. Event Reporting

For the Quarter (July – September 2017)

Event Number	Event	Status/Outcome
17-22*	Leak testing of one sealed source standard was not completed by the due date.	A verification step will be implemented to ensure the leak testing is completed.
17-23*	Prescribed information was inadvertently exported via email without the proper export license.	An export license has been received for future exports of this prescribed information. Nordion will be implementing new measures to further label and safeguard all export controlled information.
17-24*	Two Type B packages were dropped from a fork lift during handling/transfer at a Canadian airport. Minor damage was noted on the packages.	Nordion advised there was no negative impact on the radiation fields as a result of the event. No further action is required by Nordion as the event occurred at the airport.
17-25*	Compressed air sample was shipped without a Dangerous Goods label on the package and stopped in transit.	The package was labeled and continued to destination. Nordion personnel were reminded of category label requirements.

** There was no impact to health, safety, environment or security as a result of these events*