



Nordion Inc. Event Reporting
for the Quarter (April – June 2013)

Event Number	Event Title	Comment
13-12	Ir-192 exported exceeded export license by 1.5%	Additional systems have been implemented to ensure compliance with export permit.
13-13	Transport Index was not listed on the shipping documents	Nordion employees have been made aware, no further corrective action required
13-16	Intermittent Klaxon Malfunction	Changes to wiring and the installation of booster panels have been made to ensure correct amperage requirements of the Klaxon Alarm Panel are met.
13-17	Chiller Release (12.25 kg R-22)	A total of four electronic expansion valves have been replaced. Each has two circuits and both were replaced in this unit as well as in a similar unit.
13-18	Damaged F458/F251	Nordion provided feedback to the carrier.