

Nordion (Canada) Inc. Event Reporting

For the Quarter (Oct – Dec 2019)

Event Number	Event	Status/Outcome
19-16*	A bucket containing sealed sources became temporarily caught while in the elevator between Pool 13 and the hotcell.	The elevator is designed to provide adequate shielding during movement of sources, so there was no increased radiation risk. The process for elevator usage has been reviewed and revised to prevent further incidents.
19-17*	Leak testing of 3 items of depleted uranium were not completed within the required timeline.	The process for issuing work orders related to leak testing was reviewed and revised to ensure completion within the required time.
19-18*	A Type A package containing a single patient dose of Y-90 was damaged in transit.	The damage was contained to the package, as designed, and did not impact the product. There was no contamination as a result
19-19*	A damaged Type A (F-461) package was received at Nordion.	The damage was contained to the package, as designed, and did not impact the product There was no contamination as a result

** There was no impact to health, safety, environment or security as a result of these events*