

Nordion (Canada) Inc. Event Reporting
For the Quarter (Jan to Mar 2022)

Event Number	Event	Status/Outcome
22-01*	Sample chamber stuck on Gammacell 220	The sample chamber was unable to engage in the fully down chamber position due to a coolant tube that got caught during motion. The sources remain stationary in the Gammacell 220 during chamber movement. Going forward, the tube length will be controlled and hung on the hook to prevent future mishaps. There was no impact to people or environment.
22-02*	Inaccurate reporting of sealed source tracking system	Two incoming shipments reported to the CNSC-SSTS group in 2021 were found to have incorrect origin information. Upon discovering the error, an investigation initiated, and a correction was sent to the CNSC-SSTS.
22-03*	Missed sealed source model on CNSC export license	A shipment departed Nordion facility without the correct sealed source model listed on the CNSC export license. The missing source model was inadvertently omitted overlooked during the license application. Nordion is reviewing the management process including verification of source model information against export licenses and corrective actions are underway to avoid future reoccurrences.

** There was no impact to health, safety, environment or security as a result of these events*