

Nordion (Canada) Inc. Event Reporting
For the Quarter (July to September 2025)

| Velocity Incident Number | Event | Status/Outcome |
|--------------------------|---|---|
| IN-20250710-002* | Outer cardboard box damaged during transit; contents secure | Nordion, as a carrier, picked up a Type A package from the Ottawa airport and delivered it to BWXT Medical. The outer cardboard box had minor damage that did not affect the package's safety or integrity. The damage occurred before Nordion received the shipment. BWXT Medical is responsible for investigating the issues and taking any necessary corrective actions. |
| IN-20250904-004* | Discoloration of creek water | During a routine inspection, the creek water on Nordion's site was observed to be muddy. An investigation confirmed that the cause of the muddy creek water was due to a break in the site water main that supplies fresh city water to Nordion's site. The break was repaired, and the water main will be replaced. |

** There was no impact to health, safety, environment or security as a result of these events*