

Nordion (Canada) Inc. Event Reporting
For the Quarter (April to June 2026)

Velocity Incident Number	Event	Status/Outcome
IN-20260509-002*	Nordion transport package received from a customer in an incorrect loading configuration	Nordion received a transport package from a customer with an incorrect configuration. There were no radiation fields above shipping limits and there was no impact to safety. Nordion has discussed the matter with the customer and will reinforce the correct loading procedure and configuration checklist to clarify requirements with the customer. Nordion will also require the customer to provide configuration confirmation for review and approval prior to future loadings to mitigate future occurrences.

** There was no impact to health, safety, environment or security as a result of these events*