

**Nordion (Canada) Inc. Event Reporting**

For the Quarter (April – June 2019)

Event Number	Event	Status/Outcome
19-07*	A customer detected Cs-137 in their irradiator pool shortly after receiving a Nordion shipment.	Nordion reviewed the processes that were ongoing while the customer order was being prepared, loaded and packaged. No Cs-137 contamination was found during routine monitoring activities. No further corrective action required.
19-08*	Loss of power to a limited number of systems in Cobalt Operations.	Situation attributed to a tripped breaker, which was reset, returning equipment to normal operation.

*\* There was no impact to health, safety, environment or security as a result of these events*