



Nordion Inc. Event Reporting

For the Quarter (January – March 2015)

Event Number	Event	Status/Outcome
15-01*	A transport package from a supplier was shipped with unauthorized contents.	Shipment received from supplier included an unsealed capsule. Package certification requires that capsules are sealed. Currently under investigation.
15-02*	Nordion did not submit reports to the Canadian Nuclear Safety Commission (CNSC) within the prescribed 21 day timeline.	Currently under investigation.
15-03*	A transport package was found to have a damaged tie-down ring when received at the consignee's site.	Container has been returned to Nordion for repair. Nordion has expanded inspections to include review of the tie-down ring.
15-04*	Missed submitting Post Shipment Verification (PSV) for two Ir-192 shipments to full distribution list at the CNSC.	Missed contacts received PSV upon awareness of oversight. Corrective actions have been implemented.
15-06	Exterior Security Breach	An external security fence was cut but no damage or loss to the facility occurred. The incident was reported to local authorities for further investigation.

*** There was no impact to health, safety, environment or security as a result of these events**