

Nordion (Canada) Inc. Event Reporting
For the Quarter (Oct to Dec 2020)

Event Number	Event	Status/Outcome
20-31*	Missing Type A package	A Type A package containing a patient dose of Y-90 was not received by the consignee on the expected day. It was confirmed the package had been delivered to the site. The consignee located the missing package one day later. The package and shielding remained in place at all times.
20-32*	Package Limit Exceeded	During loading of a shipment of sealed sources at a customer site, it was noted that one of the sources was not the correct serial number. An investigation revealed that an incorrect source had been inadvertently switched during loading with the expected source. This incident was investigated initially due to the exceedance of the export license activity limits. In discussions with the CNSC, it was noted that the incident also required a report to the CNSC as the package limit for activity was exceeded (by 0.09%). There was no safety impact to employees or the public.

** There was no impact to health, safety, environment or security as a result of these events*