

Nordion (Canada) Inc. Event Reporting
For the Quarter (Apr to Jun 2021)

Event Number	Event	Status/Outcome
21-05*	Late filing for the import of controlled information	During a routine review of import processes, it was identified that an annual report for the import of controlled information was inadvertently missed during submission of multiple import reports. The report was subsequently submitted.
21-06*	Contamination found on source holder of a return shipment	During routine inspection, a contaminated source holder was identified from returned shipment from a customer. Contamination was managed under Nordion's contamination control procedure and was contained to the shipment. Nordion has discussed this issue with the CNSC. There was no material risk to individuals handling the shipment, public or environment.
21-07*	Damaged ocean freight containers	Two flat racks received from a return shipment were found slightly damaged. No damage occurred to the packages contained on the flat racks. The shipper was informed, and repair has been arranged. These damages do not pose any risk to the public or environment.
21-08*	Discrepancy on package content	A Type B package received from a supplier was found with a missing Y-90 ampoule. It was determined that the supplier failed to place the Y90 ampoule in the package for shipment and the material was still within the supplier's hot cell. This has no impact to the public or the environment.
21-09*	BMS server issue	The computer server for the Building Management System went off-line on two occasions. Nordion personnel were able to bring the server back online the same day on both occasions. Monitoring of safety systems and alarms was not impeded by this issue and the facility continued to operation safely.

** There was no impact to health, safety, environment or security as a result of these events*