

Nordion (Canada) Inc. Event Reporting
For the Quarter (Jul to Sept 2022)

Event Number	Event	Status/Outcome
22-09*	Admin Level 2 dose exceedance with Contractor	During a review of Q2 dosimetry reports a dose rate was reported that exceeded an internal Nordion administrative level. Investigation determined that this was likely not a true dose but a measurement artifact, such as improper background subtraction.
22-10*	Water in loaded package	A shipment was received from the field with water inside the package cavity. There was no resulting dose to personnel receiving the package. Procedures for preparation for shipment and drying have been reviewed and modified to ensure water is removed from the package cavity prior to shipment.
22-12*	Missing TLDs during shipment	A shipment of monthly personnel dosimeters sent for measurement were misplaced by the shipping carrier. Personnel doses for this period were subsequently obtained using the electronic dosimeters worn by personnel. Measured doses were all within expected ranges.

** There was no impact to health, safety, environment or security as a result of these events*