

Nordion (Canada) Inc. Event Reporting
For the Quarter (Apr to Jun 2023)

Event Number	Event	Status/Outcome
23-03*	Dose Action level Triggered	An employee's monthly whole-body dose triggered Nordion's established action level. Action levels are conservatively established by Nordion well below regulatory limits and are used to continuously improve Nordion's strong safety programs. An investigation found that the observed dose level was caused by a slightly contaminated pen that was in the employee's lab coat pocket next to the TLD badge. As a corrective action, procedures have been revised to include enhanced monitoring of employee lab coats for contamination. The employee dose was well below the regulatory limits and the incident posed no risk to the environment or the public.

** There was no impact to health, safety, environment or security as a result of these events*